

Metric Measurement Notes

Measuring Lengths

- 1) line ruler up at the zero mark
(may not be the end of the ruler!)
- 2) make sure the ruler is aligned
with the line you are measuring
- 3) find the last number marked on the
ruler, closest to the end of the line.
That's the # of cm's!
- 4) count the number of tick marks
past the number found in step #3.
That is the number of extra mm's
OR you can put that number after
a decimal when measuring in cm's